

Photo 23. 1st floor auditorium - General view of auditorium ceiling




Photo 24. 1st floor auditorium - damaged acoustical plaster above stage



Photo 25. 1st floor auditorium - General view of stage curtains adjacent to breaker box
(general location of dust sample #1)




Photo 26. 4th floor elevator lobby - General view of acoustical plaster in lobby




Photo 27. 4th floor, SW corner hallway - Close-up of damaged acoustical plaster on 4th floor south side